

Fig. 1a




Fig. 1b






Fig. 1c*Fig. 1d*

Fig. 2a




Fig. 2b






Fig. 3a**Fig. 3b**

Fig. 3c




Fig. 3d




Fig. 4




Fig. 5






Fig. 6*Fig. 7*

Fig. 8a

$$\begin{aligned} dx(x, y) &< 0 \\ dy(x, y) &> 0 \\ 0 < Ec(x, y) < 90 \end{aligned}$$




Fig. 8b

$$\begin{aligned} dx(x, y) &> 0 \\ dy(x, y) &> 0 \\ 90 < Ec(x, y) < 180 \end{aligned}$$




Fig. 8e

$$\begin{aligned} dx(x, y) &> 0 \\ dy(x, y) &= 0 \\ Ec(x, y) &= 180 \end{aligned}$$




Fig. 8f

$$\begin{aligned} dx(x, y) &= 0 \\ dy(x, y) < 0 \\ Ec(x, y) &= 270 \end{aligned}$$




Fig. 8c

$$\begin{aligned} dx(x, y) &> 0 \\ dy(x, y) < 0 \\ 180 < Ec(x, y) < 270 \end{aligned}$$




Fig. 8g

$$\begin{aligned} dx(x, y) &< 0 \\ dy(x, y) &= 0 \\ Ec(x, y) &= 0 \end{aligned}$$




Fig. 8h

$$\begin{aligned} dx(x, y) &= 0 \\ dy(x, y) > 0 \\ Ec(x, y) &= 90 \end{aligned}$$




Fig. 8d

$$\begin{aligned} dx(x, y) &< 0 \\ dy(x, y) < 0 \\ 270 < Ec(x, y) < 360 \end{aligned}$$






Fig. 9**Fig. 10**

Fig. 11a




Fig. 11b




Fig. 11c




Fig. 11d





Fig. 12a






Fig. 13a




Fig. 13b




Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig. 18

